

STOFFER MED VELDIG HØY BEKYMRING (SVHC) INFORMASJON OM TRYGG BRUK

REACH-ARTIKKEL 33-INFORMASJON OM STOFFER MED VELDIG HØY BEKYMRING (SVHC - SUBSTANCES OF VERY HIGH CONCERN)

Kjære kunde,

REACH-reglene (reg. EC 1907/2006) artikkel 33 (1) har til hensikt å la kunder av leverte produkter ta relevante risiko-forhåndsregler som følge av tilstedeværelse av produkter med stoffer med veldig høy bekymring (SVHC-er) listet opp i den nåværende kandidatlisten til autorisasjon, for å sikre trygg bruk.

FORDstøtter de underliggende målene til REACH generelt og artikkel 33(1) spesielt. Den stemmer overens med vår selvpålagte forpliktelse til å fremme ansvarlig produksjon, håndtering og bruk av våre produkter.

Identifisering av SVHC-er

Så langt vi kjenner til, basert på informasjon mottatt fra vår leveringskjede og vår egen produksjonsinformasjon, er SVHC-er tilstede i komponentprodukter med mer enn 0,1 % w/w vist på den relevante "SVHC-listen" for det/den spesifikke kjøretøyet/delen.

Spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er

Hvis aktuelt er spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er lagt til ved den relevante "SVHC-listen" for det/den spesifikke kjøretøyet/delen.

Generell informasjon om trygg bruk av produkter

Hvert FORD-kjøretøy er utstyrt med en eierhåndbok, som inkluderer informasjon om trygg bruk for eieren/brukeren av kjøretøyet. FORDs informasjon om reparasjon og service av kjøretøy og originale deler inkluderer også informasjon om trygg bruk for service-medarbeidere.

Når det er tilstede i deler av dette kjøretøyet vil SVHC-er vist i den relevante "SVCH-listen" for det/den spesifikke kjøretøyet/delen være inkorporert på en slik måte at potensiell eksponering for kunder er minimert, og fare ovenfor mennesker og miljø kan ekskluderes så lenge kjøretøyet og dets deler brukes som tiltenkt, og enhver reparasjon, service og vedlikehold blir utført i henhold til tekniske instruksjoner for slike aktiviteter, industristandarder og god praksis.

Et kjøretøy som skal vrakes kan kun leveres lovlig innen EU til et autorisert behandlingsanlegg (Authorised Treatment Facility - ATF). Kjøretøydeler skal kun avhendes i henhold til gjeldende lokale lover og etter veiledning fra lokale myndigheter.

Modell: Ford Bronco Sport

SVHC-liste basert på ECHA-kandidatliste fra 1. januar 2026

Spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er

Ingen spesifikk informasjon om trygg bruk er nødvendig - følg generell informasjon om trygg bruk av produkter.

Commodity	REACH SVHCs
Accessories	1,2-Dimethoxyethane [110-71-4]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Di-(2-ethylhexyl)phthalat [117-81-7]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Air Induction	2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
AIS - Air Cleaner and Low Pressure Ducts	2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Appliques (Pillar, Decklid, Roof)	Lead [7439-92-1]
Auto Transmission	Lead [7439-92-1]
Auto Transmission Cooler and Lines	Lead [7439-92-1]
Auto Transmission Shifter	Lead [7439-92-1]
Body and Security Electronics	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Body Covers and Ornamentation	C,C'-azodi(formamide) [123-77-3]
Body Structure - Decklid/Liftgate (incl Hinge/Supt)	Dicyclohexyl-phthalate [84-61-7]
Brakes	Lead [7439-92-1]
	Tris(nonylphenyl)phosphite [26523-78-4]
Bumpers and Spoilers	Di-(2-ethylhexyl)phthalat [117-81-7]
CCB (IP cross car beam)	Lead [7439-92-1]
Climate	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	4,4'-Isopropylidenediphenol [80-05-7]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
	Melamine [108-78-1]
Closures and Lids Mechanisms	Boric acid [10043-35-3]
	Lead [7439-92-1]

Cooling	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Dressed Engine	Lead [7439-92-1]
Driveline	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Boric acid [10043-35-3]
	Decamethylcyclopentasiloxane [541-02-6]
	Lead [7439-92-1]
Driveline (Powerpack)	Lead [7439-92-1]
Driver Controls	Lead [7439-92-1]
Dynamic Sealing	Imidazolidine-2-thione [96-45-7]
EDS	Cobalt sulphate [10124-43-3]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Exhaust Cold End	Lead [7439-92-1]
Exterior Lighting	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	Tris(nonylphenyl)phosphite [26523-78-4]
Front / Rear Door Trim	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Ethoxyethanol [110-80-5]
Fuel	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
GOR and Radiator Support	Lead [7439-92-1]
Headliner / Sunvisor	Lead [7439-92-1]
IP and Console	Bumetrizole [3896-11-5]
IP Substrate and Ducts	Bumetrizole [3896-11-5]
Lower Body Structure	Dicyclohexyl-phthalate [84-61-7]
Mirrors	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Cyclohexane-1,2-dicarboxylic anhydride [85-42-7]
	Lead [7439-92-1]
Multimedia	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	Octamethyltrisiloxane [107-51-7]
	TBBA [79-94-7]
Power Supply	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Powertrain Controls and Calibration	Lead [7439-92-1]
Powertrain Mounts	1-Methyl-2-pyrrolidone [872-50-4]
	Lead [7439-92-1]
Restraint	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Bumetrizole [3896-11-5]

	Lead [7439-92-1]
	TBBA [79-94-7]
Roof	Lead [7439-92-1]
Safety Electronics	Lead [7439-92-1]
Seat Belts (Front and Rear)	Lead [7439-92-1]
Seating	Decamethylcyclopentasiloxane [541-02-6]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Melamine [108-78-1]
	Octamethylcyclotetrasiloxane [556-67-2]
	Sodium borate, decahydrate [1303-96-4]
Seats - Foam - Cut and Sew	Melamine [108-78-1]
Seats - JIT	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
	Triphenyl-phosphate [115-86-6]
Seats - Structures	Lead [7439-92-1]
Shock Absorbers	Lead [7439-92-1]
Side Door Mechanisms	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
	TBBA [79-94-7]
Side Doors BIW	Cobalt sulphate [10124-43-3]
Steering	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Lead [7439-92-1]
Suspension Frames and Mountings	Lead [7439-92-1]
Switches	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Methylimidazole [693-98-1]
	Lead [7439-92-1]
	Melamine [108-78-1]
Upper Body Structure	Dicyclohexyl-phthalate [84-61-7]
Wash-Wipe	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	C,C'-azodi(formamide) [123-77-3]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Wiper Assembly (Rear, Front) & Washer System	Lead [7439-92-1]