

STOFFER MED VELDIG HØY BEKYMRING (SVHC) INFORMASJON OM TRYGG BRUK

REACH-ARTIKKEL 33-INFORMASJON OM STOFFER MED VELDIG HØY BEKYMRING (SVHC - SUBSTANCES OF VERY HIGH CONCERN)

Kjære kunde,

REACH-reglene (reg. EC 1907/2006) artikkel 33 (1) har til hensikt å la kunder av leverte produkter ta relevante risiko-forhåndsregler som følge av tilstedeværelse av produkter med stoffer med veldig høy bekymring (SVHC-er) listet opp i den nåværende kandidatlisten til autorisasjon, for å sikre trygg bruk.

FORDstøtter de underliggende målene til REACH generelt og artikkel 33(1) spesielt. Den stemmer overens med vår selvpålagte forpliktelse til å fremme ansvarlig produksjon, håndtering og bruk av våre produkter.

Identifisering av SVHC-er

Så langt vi kjenner til, basert på informasjon mottatt fra vår leveringskjede og vår egen produksjonsinformasjon, er SVHC-er tilstede i komponentprodukter med mer enn 0,1 % w/w vist på den relevante "SVHC-listen" for det/den spesifikke kjøretøyet/delen.

Spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er

Hvis aktuelt er spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er lagt til ved den relevante "SVHC-listen" for det/den spesifikke kjøretøyet/delen.

Generell informasjon om trygg bruk av produkter

Hvert FORD-kjøretøy er utstyrt med en eierhåndbok, som inkluderer informasjon om trygg bruk for eieren/brukeren av kjøretøyet. FORDs informasjon om reparasjon og service av kjøretøy og originale deler inkluderer også informasjon om trygg bruk for service-medarbeidere.

Når det er tilstede i deler av dette kjøretøyet vil SVHC-er vist i den relevante "SVCH-listen" for det/den spesifikke kjøretøyet/delen være inkorporert på en slik måte at potensiell eksponering for kunder er minimert, og fare ovenfor mennesker og miljø kan ekskluderes så lenge kjøretøyet og dets deler brukes som tiltenkt, og enhver reparasjon, service og vedlikehold blir utført i henhold til tekniske instruksjoner for slike aktiviteter, industristandarder og god praksis.

Et kjøretøy som skal vrakes kan kun leveres lovlig innen EU til et autorisert behandlingsanlegg (Authorised Treatment Facility - ATF). Kjøretøydeler skal kun avhendes i henhold til gjeldende lokale lover og etter veiledning fra lokale myndigheter.

Modell: Ford Puma

SVHC-liste basert på ECHA-kandidatliste fra 1. januar 2026

Spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er

Ingen spesifikk informasjon om trygg bruk er nødvendig - følg generell informasjon om trygg bruk av produkter.

Commodity	REACH SVHCs
Accessories	1,2-Dimethoxyethane [110-71-4]
	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Auto Transmission Shifter	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
Body and Security Electronics	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Lead [7439-92-1]
Body Covers and Ornamentation	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Bodyside, Wheel Arch, Rocker Moldings	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Brakes	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
	TBBA [79-94-7]
Bulk Materials (PMT100)	C,C'-azodi(formamide) [123-77-3]
	Dicyclohexyl-phthalate [84-61-7]
Bumpers and Spoilers	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Lead [7439-92-1]
Climate	Lead [7439-92-1]
Closures and Lids BIW	Lead [7439-92-1]
Closures and Lids Mechanisms	Lead [7439-92-1]
Console Floor/Rear	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Bumetrizole [3896-11-5]
Cooling	Lead [7439-92-1]
Dressed Engine	Lead [7439-92-1]
Driveline	Methyloxirane [75-56-9]
	Sodium borate, decahydrate [1303-96-4]
	Triphenyl-phosphate [115-86-6]
Driver Controls	Lead [7439-92-1]
EDS	4,4'-Isopropylidenediphenol [80-05-7]
	Bumetrizole [3896-11-5]

	Decamethylcyclopentasiloxane [541-02-6]
	Lead [7439-92-1]
Exhaust Cold End	Lead [7439-92-1]
Exterior Lighting	Lead [7439-92-1]
Fixed Glazing	Diboron-trioxide [1303-86-2]
Fuel	Lead [7439-92-1]
Glass Runs and Belts	Bumetrizole [3896-11-5]
Headliner / Sunvisor	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Hybrid Technology	1-Propanol, 2,3-dibromo- [96-13-9]
	Lead [7439-92-1]
Interior Trim	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
IP and Console	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	C,C'-azodi(formamide) [123-77-3]
	Triphenyl-phosphate [115-86-6]
IP Finish Panels/Registers	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Latches - Hood, Decklid and Liftgate Latches	Lead [7439-92-1]
Latches - Side Door/Latch Mini Module	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Lower Body Structure	Dicyclohexyl-phthalate [84-61-7]
	Lead [7439-92-1]
Manual Transmission	Lead [7439-92-1]
Manual Transmission Shifter	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Mirrors	Lead [7439-92-1]
Multimedia	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	Melamine [108-78-1]
	N,N-Dimethylacetamide [127-19-5]
Overhead Console	Lead [7439-92-1]
Pedals	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Power Supply	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Powertrain Controls and Calibration	Lead [7439-92-1]
Powertrain Mounts	Lead [7439-92-1]
Restraint	Dicyclohexyl-phthalate [84-61-7]
	Disodium-octaborate [12008-41-2]
	Lead [7439-92-1]
Roof	Lead [7439-92-1]

Seating	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
	Triphenyl-phosphate [115-86-6]
Seats - Foam - Cut and Sew	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Side Door Mechanisms	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
	TBBA [79-94-7]
Steering	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Suspension Frames and Mountings	Imidazolidine-2-thione [96-45-7]
	Phenol, dodecyl-, branched [121158-58-5]
Suspension Link Components	Imidazolidine-2-thione [96-45-7]
Switches	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Wash-Wipe	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Wheels Tires Jacks and Equipment	Lead [7439-92-1]
Window Regulator	Lead [7439-92-1]