

STOFFER MED VELDIG HØY BEKYMRING (SVHC) INFORMASJON OM TRYGG BRUK

REACH-ARTIKKEL 33-INFORMASJON OM STOFFER MED VELDIG HØY BEKYMRING (SVHC - SUBSTANCES OF VERY HIGH CONCERN)

Kjære kunde,

REACH-reglene (reg. EC 1907/2006) artikkel 33 (1) har til hensikt å la kunder av leverte produkter ta relevante risiko-forhåndsregler som følge av tilstedeværelse av produkter med stoffer med veldig høy bekymring (SVHC-er) listet opp i den nåværende kandidatlisten til autorisasjon, for å sikre trygg bruk.

FORDstøtter de underliggende målene til REACH generelt og artikkel 33(1) spesielt. Den stemmer overens med vår selvpålagte forpliktelse til å fremme ansvarlig produksjon, håndtering og bruk av våre produkter.

Identifisering av SVHC-er

Så langt vi kjenner til, basert på informasjon mottatt fra vår leveringskjede og vår egen produksjonsinformasjon, er SVHC-er tilstede i komponentprodukter med mer enn 0,1 % w/w vist på den relevante "SVHC-listen" for det/den spesifikke kjøretøyet/delen.

Spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er

Hvis aktuelt er spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er lagt til ved den relevante "SVHC-listen" for det/den spesifikke kjøretøyet/delen.

Generell informasjon om trygg bruk av produkter

Hvert FORD-kjøretøy er utstyrt med en eierhåndbok, som inkluderer informasjon om trygg bruk for eieren/brukeren av kjøretøyet. FORDs informasjon om reparasjon og service av kjøretøy og originale deler inkluderer også informasjon om trygg bruk for service-medarbeidere.

Når det er tilstede i deler av dette kjøretøyet vil SVHC-er vist i den relevante "SVCH-listen" for det/den spesifikke kjøretøyet/delen være inkorporert på en slik måte at potensiell eksponering for kunder er minimert, og fare ovenfor mennesker og miljø kan ekskluderes så lenge kjøretøyet og dets deler brukes som tiltenkt, og enhver reparasjon, service og vedlikehold blir utført i henhold til tekniske instruksjoner for slike aktiviteter, industristandarder og god praksis.

Et kjøretøy som skal vrakes kan kun leveres lovlig innen EU til et autorisert behandlingsanlegg (Authorised Treatment Facility - ATF). Kjøretøydeler skal kun avhendes i henhold til gjeldende lokale lover og etter veiledning fra lokale myndigheter.

Modell: Ford Explorer

SVHC-liste basert på ECHA-kandidatliste fra 1. januar 2026

Spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er

Ingen spesifikk informasjon om trygg bruk er nødvendig - følg generell informasjon om trygg bruk av produkter.

Commodity	REACH SVHCs
Accessories	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	Lead [7439-92-1]
Air Induction	Lead [7439-92-1]
Appliques (Pillar, Decklid, Roof)	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	C,C'-azodi(formamide) [123-77-3]
Auto Transmission	Boric acid [10043-35-3]
	Lead [7439-92-1]
Auto Transmission Cooler and Lines	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Auto Transmission Shifter	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Body and Security Electronics	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	1-Propanol, 2,3-dibromo- [96-13-9]
	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Boric acid [10043-35-3]
	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
Body Side InteriorTrim (Hard Trim)	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Melamine [108-78-1]
Body Structure - Floor Pan - Rear Floor	C,C'-azodi(formamide) [123-77-3]
Body Structure - Front Fender	Dicyclohexyl-phthalate [84-61-7]
Brakes	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Dicyclohexyl-phthalate [84-61-7]

	Lead [7439-92-1]
Bumpers and Spoilers	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	TBBA [79-94-7]
Climate	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Cobalt-dinitrate [10141-05-6]
	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
	Tris(nonylphenyl)phosphite [26523-78-4]
Closures and Lids BIW	Lead [7439-92-1]
Closures and Lids Mechanisms	Octamethylcyclotetrasiloxane [556-67-2]
	Triphenyl-phosphate [115-86-6]
Console Floor/Rear	Lead [7439-92-1]
Cooling	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Dressed Engine	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Driveline	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Driveline (Powerpack)	Boric acid [10043-35-3]
Driver Controls	Lead [7439-92-1]
EDS	Boric acid [10043-35-3]
	Decamethylcyclopentasiloxane [541-02-6]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
	Tris(2-methoxyethoxy)vinylsilane [1067-53-4]
Exhaust Cold End	Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8]
	Lead [7439-92-1]
Exterior Lighting	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	Silicic acid, lead salt [11120-22-2]
	TBBA [79-94-7]
Fascia Grille - Radiator	Lead [7439-92-1]
Front / Rear Door Trim	Cobalt-sulfate-heptahydrate [10026-24-1]
	Lead [7439-92-1]
Fuel	Lead [7439-92-1]
Glass Runs and Belts	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
GOR and Radiator Support	Lead [7439-92-1]
Headliner / Sunvisor	Hexahydromethylphthalic-anhydride [25550-51-0]

Hybrid Technology	Lead [7439-92-1]
	Silicic acid, lead salt [11120-22-2]
Interior Trim	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	Tris(nonylphenyl)phosphite [26523-78-4]
IP and Console	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
IP Finish Panels/Registers	Lead [7439-92-1]
IP Substrate and Ducts	Lead [7439-92-1]
Latches - Hood, Decklid and Liftgate Latches	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Lower Body Structure	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	C,C'-azodi(formamide) [123-77-3]
Luggage and Interior Cargo Management/Covers	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Mirrors	Lead [7439-92-1]
Multimedia	Boric acid [10043-35-3]
	Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4]
	Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8]
	Lead [7439-92-1]
	Melamine [108-78-1]
	Octamethyltrisiloxane [107-51-7]
Overhead Console	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
Pedals	Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8]
Power Supply	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Cobalt(II) nitrate hexahydrate [10026-22-9]
	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Powertrain Controls and Calibration	Lead [7439-92-1]
Powertrain Mounts	1-Methyl-2-pyrrolidone [872-50-4]
	Lead [7439-92-1]
Restraint	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Roof	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Safety Electronics	1,3-Propanesultone [1120-71-4]
	Lead [7439-92-1]
	TBBA [79-94-7]

Seat Belts (Front and Rear)	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Seating	Lead [7439-92-1]
	Melamine [108-78-1]
	Phenol, dimethyl-, phosphate (3:1) [25155-23-1]
	Sodium borate, decahydrate [1303-96-4]
	Triphenyl-phosphate [115-86-6]
Seats - Foam - Cut and Sew	Triphenyl-phosphate [115-86-6]
Seats - Structures	Lead [7439-92-1]
	N,N-Dimethylacetamide [127-19-5]
	Sodium borate, decahydrate [1303-96-4]
Side Door Mechanisms	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
Spoiler	Lead [7439-92-1]
Static Sealing	C,C'-azodi(formamide) [123-77-3]
Steering	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Suspension Frames and Mountings	Lead [7439-92-1]
Switches	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
	2-Methylimidazole [693-98-1]
	4,4'-Isopropylidenediphenol [80-05-7]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Transmission - Auto	Lead [7439-92-1]
Upper Body Structure	C,C'-azodi(formamide) [123-77-3]
	Triphenyl-phosphate [115-86-6]
Wash-Wipe	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
Wheels Tires Jacks and Equipment	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	Lead [7439-92-1]
	Melamine [108-78-1]
Window Regulator	Lead [7439-92-1]