

STOFFER MED VELDIG HØY BEKYMRING (SVHC) INFORMASJON OM TRYGG BRUK

REACH-ARTIKKEL 33-INFORMASJON OM STOFFER MED VELDIG HØY BEKYMRING (SVHC - SUBSTANCES OF VERY HIGH CONCERN)

Kjære kunde,

REACH-reglene (reg. EC 1907/2006) artikkel 33 (1) har til hensikt å la kunder av leverte produkter ta relevante risiko-forhåndsregler som følge av tilstedeværelse av produkter med stoffer med veldig høy bekymring (SVHC-er) listet opp i den nåværende kandidatlisten til autorisasjon, for å sikre trygg bruk.

FORDstøtter de underliggende målene til REACH generelt og artikkel 33(1) spesielt. Den stemmer overens med vår selvpålagte forpliktelse til å fremme ansvarlig produksjon, håndtering og bruk av våre produkter.

Identifisering av SVHC-er

Så langt vi kjenner til, basert på informasjon mottatt fra vår leveringskjede og vår egen produksjonsinformasjon, er SVHC-er tilstede i komponentprodukter med mer enn 0,1 % w/w vist på den relevante "SVHC-listen" for det/den spesifikke kjøretøyet/delen.

Spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er

Hvis aktuelt er spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er lagt til ved den relevante "SVHC-listen" for det/den spesifikke kjøretøyet/delen.

Generell informasjon om trygg bruk av produkter

Hvert FORD-kjøretøy er utstyrt med en eierhåndbok, som inkluderer informasjon om trygg bruk for eieren/brukeren av kjøretøyet. FORDs informasjon om reparasjon og service av kjøretøy og originale deler inkluderer også informasjon om trygg bruk for service-medarbeidere.

Når det er tilstede i deler av dette kjøretøyet vil SVHC-er vist i den relevante "SVCH-listen" for det/den spesifikke kjøretøyet/delen være inkorporert på en slik måte at potensiell eksponering for kunder er minimert, og fare ovenfor mennesker og miljø kan ekskluderes så lenge kjøretøyet og dets deler brukes som tiltenkt, og enhver reparasjon, service og vedlikehold blir utført i henhold til tekniske instruksjoner for slike aktiviteter, industristandarder og god praksis.

Et kjøretøy som skal vrakes kan kun leveres lovlig innen EU til et autorisert behandlingsanlegg (Authorised Treatment Facility - ATF). Kjøretøydeler skal kun avhendes i henhold til gjeldende lokale lover og etter veiledning fra lokale myndigheter.

Modell: Ford Mustang MACH E

SVHC-liste basert på ECHA-kandidatliste fra 1. januar 2026

Spesifikk informasjon om trygg bruk av produkter som inneholder SVHC-er

Ingen spesifikk informasjon om trygg bruk er nødvendig - følg generell informasjon om trygg bruk av produkter.

Commodity	REACH SVHCs
Accessories	1,2-Dimethoxyethane [110-71-4]
	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Lead [7439-92-1]
	Melamine [108-78-1]
	Sodium borate, decahydrate [1303-96-4]
Air Bag Module- Pass Side	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Auto Transmission	Lead [7439-92-1]
Body and Security Electronics	4,4'-Isopropylidenediphenol [80-05-7]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
	N,N-Dimethylacetamide [127-19-5]
	TBBA [79-94-7]
Body Covers and Ornamentation	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
Body Structure - Decklid/Liftgate (incl Hinge/Supt)	Lead [7439-92-1]
Body Structure - Front End Structure	C,C'-azodi(formamide) [123-77-3]
Bodyside, Wheel Arch, Rocker Moldings	Lead [7439-92-1]
Brakes	2-Methylimidazole [693-98-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
	Tris(nonylphenyl)phosphite [26523-78-4]
Bumpers and Spoilers	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Chassis Electronics	Lead [7439-92-1]

Climate	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Bumetrizole [3896-11-5]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
Closures and Lids BIW	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Closures and Lids Mechanisms	Lead [7439-92-1]
	TBBA [79-94-7]
Cooling	Lead [7439-92-1]
Driveline	Lead [7439-92-1]
Driver Controls	Lead [7439-92-1]
EDS	Dioctyltin dilaurate [3648-18-8]
	Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether [9002-93-1]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Electrified Drivetrain Systems	Lead [7439-92-1]
Exterior Lighting	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
	TBBA [79-94-7]
Fixed Glazing	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Front / Rear Door Trim	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
Functional and Black Trim	Lead [7439-92-1]
Glass Runs and Belts	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	4,4'-Isopropylidenediphenol [80-05-7]
Headliner / Sunvisor	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Hybrid Technology	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
	N,N-Dimethylacetamide [127-19-5]
Interior Trim	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
IP and Console	Lead [7439-92-1]

	Triphenyl-phosphate [115-86-6]
IP Finish Panels/Registers	Lead [7439-92-1]
	Nonylphenol [25154-52-3]
Lower Body Structure	C,C'-azodi(formamide) [123-77-3]
	Dicyclohexyl-phthalate [84-61-7]
Mirrors	Dodecamethylcyclhexasiloxane [540-97-6]
	Lead [7439-92-1]
	Octamethyltrisiloxane [107-51-7]
Multimedia	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
	N,N-Dimethylacetamide [127-19-5]
	Triphenyl-phosphate [115-86-6]
	Tris(nonylphenyl)phosphite [26523-78-4]
Power Supply	Lead [7439-92-1]
Powertrain Controls and Calibration	Lead [7439-92-1]
Restraint	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Lead [7439-92-1]
	TBBA [79-94-7]
Safety Electronics	Lead [7439-92-1]
Sealing - Glass Runs and Belt Moldings	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Seat Belts (Front and Rear)	Lead [7439-92-1]
Seating	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether [9002-93-1]
	Lead [7439-92-1]
	Melamine [108-78-1]
Seats - Structures	Lead [7439-92-1]
	Sodium borate, decahydrate [1303-96-4]
Side Door Mechanisms	Lead [7439-92-1]
Side Doors BIW	C,C'-azodi(formamide) [123-77-3]
Static Sealing	C,C'-azodi(formamide) [123-77-3]
	Dicyclohexyl-phthalate [84-61-7]
Steering	Lead [7439-92-1]
Suspension Frames and Mountings	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
	Nonylphenol [25154-52-3]
Switches	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	TBBA [79-94-7]
Upper Body Structure	Dicyclohexyl-phthalate [84-61-7]

Wash-Wipe	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]